

## **E Meter Test Equipment**

# CheckSystem 2.3

Three-phase test system with class 0.2 reference standard and integrated three-phase current source up to 16 A



The CheckSystem 2.3 portable test system consists of an integrated three-phase current source and a three-phase electronic reference standard of accuracy class 0.2. Characteristic features of the CheckSystem 2.3 are its wide measuring range, high accuracy and high tolerance to unwanted external influences.

The CheckSystem 2.3 allows the monitoring of meter installations as well as analysis of the local mains conditions.

#### Advantages

- Easy verification of meters under precise load conditions, using the built-in, compact, current source
- Automatic operation using predefined load points without the need for an external PC
- Internal memory for storage of measurement results and customer data
- Display of vector diagram and phase sequence for analysis of the supply conditions
- User-friendly system for data input and operation of source and reference meter
- The system may be used either as a stand-alone reference standard meter, or together with the integrated power source

#### **Functions**

- Independent generation of single or three phase current loading conditions for verification of meters using the incoming supply voltage
- Active, reactive and apparent energy measurement for three phase, 3- or 4-wire systems, with integrated error calculator and pulse output
- Vector diagram, harmonics spectrum, wave form and rotary field display for analysis of the mains conditions
- Voltage measurement
- Current measurement directly or with UCT clamp-on CT's
- Active, reactive and apparent power measurement
- Phase angle, power factor and frequency measurement

#### **Options**

- Software CALSOFT for memory readout, online data logging, presentation and printout of results and customer data and for automatic test sequences.
- Set of 3 UCT120.3 clamp-on CT 120A (active error compensated)

#### Technical Data CheckSystem 2.3 (class 0.2)

#### General

Auxiliary supply:	Power may be taken from the auxiliary supply or the measuring circuit at:  88 VACmin 264 VACmax / 47 63 Hz 125 VDCmin 372 VDCmax Protection: up to 440VACmax		
Voltages Operation	10 V 300 V		
Synchronisation	10 V 300 V		
Power consumption:	max.150 VA		
Housing:	Hard Plastic		
Dimensions:	W 273 x H 247 x D 178 mm		
Weight:	approx. 6.2 kg (excl. accessories)		
Operation temperature:	-10 °C +50 °C		
Storage temperature:	-20 °C +60 °C		
Relative humidity:	≤ 85% at Ta ≤ 21°C		
	≤ 95% at Ta ≤ 25°C, 30 days / year spread		

Safety	CE certified
--------	--------------

Isolation protection:	IEC 61010-1:2001
Measurement Category:	300V CAT III
Degree of protection:	IP-65 (housing closed)
	IP-30 (housing open)

#### **CURRENT SOURCE**

Current Range	1 mA 16 A				
Output power	15 VA (per phase)				
	Internal Ranges Smax / Umax				
	1 mA 6 mA 10 mVA / 1.67				
	6 mA 60 mA 100 mVA / 1.67 60 mA 0.6 A 1 VA / 1.67 0.6 A 6 A 10 VA / 1.67				
	6 A 16 A 15 VA / 0.94				
Resolution	0.2 % of end of internal range				
Accuracy	≤ 0.2 % of end of internal range				
Distortion Factor	≤ 0.8 %				
Stability	≤ 0.03 % (30 min.)				
	≤ 0.1 % (1 h)				
Load Regulation	≤ 0.01 % (from 0 % 100 % load)				
Power Factor of Load	1 – 0.1 ind.				
Bandwidth	30 Hz 1 kHz (-3 dB)				
Phase Angle	Range Accuracy Resolu		lution		
	-180°+180°	± 0.2°		0.1°	
Frequency	Range	Range Accuracy		Resolution	
Mode Line (synch. to input voltage)	40 Hz-70 Hz				
Mode NUM	40 Hz-70 Hz	± 0.01	Hz	0.01	Hz

#### **REFERENCE STANDARD - Measurement Range**

Measuring Quantity	Range	Input / Sensor
Voltage (phase - neutral)	10 V 300 V	U1, U2, U3, N
Current	1 mA 16 A	I1, I2, I3
	10 mA 120 A	UCT 120.3 CT 120A

#### **REFERENCE STANDARD - Measurement Accuracy**

Voltage / Current		≤ <b>±</b> E [%] <sup>1 2</sup>	
Measuring Quantity	Range	Class 0.2	
Voltage (U1, U2, U3, N)	46 V 300 V	0.2	
	10V 46 V	1.0	
Current direct (I1, I2, I3)	10 mA 16 A	0.2	
	1 mA <u>10</u> mA	<u>0.2</u>	
Current CT 120 A UCT 120.3	100 mA 120 A	0.2	
	10 mA 100 mA	1.0	

Power / Energy Voltage:	≤ ± E [%] <sup>123</sup>	
Measuring Quantity / Input I	Range	Class 0.2
Active (P), Apparent (S) Power	er / Energy	
Direct (I1, I2, I3)	10 mA 16 A	0.2
	1 mA <u>10</u> mA	<u>0.2</u>
Current CT 120 A UCT 120.3	100 mA 120 A	0.2
	10 mA 100 mA	1.0
Reactive (Q) Power / Energy		
Direct (I1, I2, I3)	10 mA 16 A	0.4
	1 mA <u>10</u> mA	<u>0.4</u>
Current CT 120 A UCT 120.3	100 mA 120 A	0.4
	10 mA 100 mA	1.0

Influence of external magnetic  $~\leq 0.07~\%$  /  $0.5~mT^{\,3}$ fields (45 Hz ... 66 Hz):

Temperature coefficient (TC):	Range	≤ ± TC [%/°C] <sup>3</sup>
	0° C +40°C	0.02
	-10° C +50°C	0.05

Frequency / Phase Angle / Power Factor		≤ <b>±</b> E
Measuring Quantity	Range	
Frequency (f)	40 Hz 70 Hz	0.01 Hz
Phase Angle (φ)	0.00 ° 359.99°	0.1 °
Power Factor (PF)	-1.000 +1.000	0.002

- x.x: Related to the measuring value
  x.x: Related to the measuring range final value (full scale, FS),
  E(M) = FS/M \* x.x (e.g. 0.2 at FS = 46 v, E(10V) = 46/10 \* 0.2 = 0.92 %)
  Fundamental frequency in the range 45 ... 66 Hz
  S: x.x, P,Q: x.x / PF (related to apparent power), 3- and 4-wire networks

### Pulse Input / Output

REDEL 8-pole common input / output connector, suitable for scanning head SH 2003

		Juitable ic		.9	000
Input level:	4 12 VDC (24 VDC)				
Input frequency:	max. 200 kHz				
Input supply:	12 VDC	(I < 60 m	A)		
Output level:	5 V				
Pulse length:	≥ 10 µs				
Meter constant:	C = 40'000'000 / In				
Active, Reactive, Apparent [imp/kWh(kvarh,kVAh)]	The meter constant depends on the selected internal current range (In).				
	Internal current ranges In [A]				
Direct (I1, I2, I3)	0.006	0.06	0.6	6	16
Current CT 120A UCT 120.3	0.12	1.2	12	120	
Output frequency:	Example: Clamp-on CT 120 A (ln = 10 A)  C = 40'000'000 / 10 = 4'000'000 [imp/kWh]  C' = C / 3'600'000 [imp/Ws(vars, Vas)]  fo = C' *P $\Sigma$ (Q $\Sigma$ , S $\Sigma$ )  f <sub>max</sub> = 40'000'000 / (10 * 3'600'000) * 3 * 10 * 300 = 10'000 [imp/s]				

**Group exporter: Multi-Tek International** Email: mti@multitekintl.com